




### 5/16






FIG.5







FIG.7
















OCT 26 2006















OCT 2 6 2006

DOCKET NO.: 0529-1046 APPLN NO.: 10/521,739 REPLY TO NOTICE OF ALLOWABILITY OF: SEPTEMBER 11, 2006 REPLACEMENT SHEET



OCT 2 6 2006 B

DOCKET NO.: 0529-1046 APPLN NO.: 10/521,739 REPLY TO NOTICE OF ALLOWABILITY OF: SEPTEMBER 11, 2006 REPLACEMENT SHEET

